



Date: Thursday, 15/01/2009 3:15:47 PM
User: Linda Lacelle

Process Sheet

Customer : CC-DAR01 Dart Aerospace Ltd.	Drawing Name : CROSSTUBE SUPPORT CHANGE
Job Number : 44857	
Estimate Number : 13359	
P.O. Number :	Part Number : DSI9415013
This Issue : 15/01/2009 S.O. No. :	Drawing Number : DSI9415
Prsht Rev. : NC	Project Number : N/A
First Issue : / / Type : SMALL /MED FAB	Drawing Revision : A
Previous Run :	Material :
Written By : 	Due Date : 22/01/2009 Qty: 1 Um: Each
Checked & Approved By : 	
Comment : Est Rev:A 08-06-03 new issue DD verified by:EC	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0	DC	DOCUMENT CONTROL
-----	----	------------------



for JLD 09/01/15



Comment: Photocopy bluefile & type labels per PPP DSI9415-013 CHG001

809601/15

2.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1
Pick Packing Kit

3.0	D3595075450	RUBBER CUSHION .75" x 4.50
-----	-------------	----------------------------



(x)

Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)
RUBBER CUSHION .75" x 4.50
batch: *41108*

96/1/15

34

4.0	QC4	INSPECT 100% KITS FOR COMPLETENESS
-----	-----	------------------------------------



Comment: INSPECT 100% KITS FOR COMPLETENESS

809601/15

5.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



(x)

Comment: PACKAGING RESOURCE #1
Identify and pack for shipping as per PPP DSI9415-013
Location: *Draft*
PPP Rev: *96/1/15*

34

Date: Thursday, 15/01/2009 3:15:48 PM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: CROSSTUBE SUPPORT CHANGE

Job Number: 44857

Part Number: DSI9415013

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC21

FINAL INSPECTION/W/O RELEASE



09/01/15 *[Signature]*

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



mf 09-01-15